



Pacific Accessory Corporation



VCI-MBZ/E

CLS - Class 2005-2007 (w219)

E - Class 2003-2006 (w211)

SLK - Class 2005-2007 (r171)



Pacific Accessory Corporation



DISCLAIMER: Under no circumstances shall the manufacturer or the distributors of the VCI-MBZ/E parts be held liable for consequential damages sustained in connection with the VCI-MBZ/E. The manufacturer and it's distributors will not, nor will they authorize any representative or any other individual to assume obligation or liability in relation to the VCI-MBZ/E other than its replacement.

Inaccuracies or Typographical Errors: The information in these instruction could contain technical or other mistakes, inaccuracies or typographical errors. PAC may make changes to the materials in these instructions at any time without notice. The information in these instructions may be out of date, and PAC makes no commitment to update such information.



Pry up on wood trim. Put car in lower gear for easier access.



Remove bolts below switch panel



Remove bolts from radio



Remove the radio from the car



Remove 2 small screws from radio



These cables need to be disconnected



Disconnected cables



Detach the LCD from the radio



Attach original cable to the new board. Connect the new cable to the original connector



Place the new board inside the radios case



RGB In/Out cables ready to be plugged into interface box.